JAN 14 1954

Chief, General Services

Director of Security

Renovation of Reception Areas

- 1. A recent survey conducted by the Security Office to determine the general condition of the Agency reception areas resulted in the following general findings:
  - (a) In general, the walls of the reception areas were found smudged, scarred, and in need of repainting. Rugs, floor linoleum, and floors are unkempt and dirty.
  - (b) Many of the "Receptionist" signs now posted are worn and in need of replacement. Some are either Scotch taped or thumb tacked to the wall, presenting an untidy appearance.
  - (c) Various receptionists reported that on numerous occasions the areas have been used after working hours as a combined lunch room and lounging facility. Orange peels, crumbs, pie plates, lunch bags, footprints on sides of desks, and the like have evidenced use of rooms during the night.
  - 2. The following recommendations are offered:
  - (a) Have the char force crews perform a more thorough job of dusting and cleaning.
  - (b) Adopt a uniform sign twelve inches high by fourteen inches long to be mounted on a four foot standard and placed outside the door of all reception areas. The sign should read: RECEPTIONIST VISITORS PLEASE REPORT HERE FOR PROCESSING.
  - (c) Paint those rooms which show need as indicated under Detailed Summary of Findings.



(d) Adoption of a uniform placard, twelve inches long by six inches high, to be placed on the main reception area desk, reading NO LOITERING.

## Detailed Summary of Findings

North Building - Area freshly painted; linoleum dirty and in need of repair; general cleaning of area necessary.

South Building - Area freshly painted.

Central Building - Area in need of painting and general cleaning.

Administration Building - Paint in fair condition; area clean.

Temporary Q - Front Entrance - Area needs painting; general cleaning needed.

Rear Entrance - Area needs painting and general cleaning.

Temporary M - This reception area in very good condition.

Street - This area in need of painting and general cleaning.

- Area needs painting and cleaning.

Building 13 - Area in good condition.

Building - Area in good condition.

Curie Hall - Freshly painted but in need of general cleaning.

Temporary L - Area in need of painting and general cleaning.

Temporary K - Needs painting.

25X1A

25X1A

25X1A

## Approved For Release 2001/07/12 : CIA-RDP76-04718A001000310021-5

Temporary J - Needs painting and general cleaning.

Temporary I - Needs painting and general cleaning.

Quarters I - Area needs painting and general cleaning.

Sheffield Edwards

SO/CJK:pjn (1/8/54)

Distribution:

1 - DD/A

1 - SO Files

